ECS Configuration Change Request					Page 1 of	•	Page(s)		
1. Originator	2. Log Date:	3. CCR #:	4. Re	ev:	5. Tel:	6. Rn	n #: 7. Dept.		
Derrick Clark	7/18/03	03-0511	-		301-925-1024	2028	SWIT		
8. CCR Title: TE_6A.07_HEG.01									
9. Originator Signature/Date			10. Class	0. Class 11. Type: 12. Need Date: 18July03			Date: 18July03		
Derrick Clark /s/ 07/18/03			II		CR				
13. Office Manager Signature/Date			14. Categor	ry of	Change: 15. Priority: (If "Emergency" fill in Block 27).		,"		
Louis Swentek /s/ 0	Other Till In Block 27). Emergency								
• • •			7. Schedule 18. Cl(s) ampact:			Affected:HEG			
19. Release Affected by this Change: 6A 20. Date due 18July					21. Estimated Cost: None - Under 100K				
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:									
23. Problem: (use additional Sheets if necessary) Heg tool does not handle data that crosses the international dateline properly. Lack of shortname in the metadata prevents user from using HEG									
C									
24. Proposed Solution: (use additional sheets if necessary) Deliver TE_6A.07_HEG.01 to all DAACs. NCR 37567 Added functionality to handle data that crosses the international dataline. NCR 37800 Added functionality to have hegtool ignore warnings of no shortname in an Hdf-Eos file.									
25. Alternate Solution: (use additional sheets if necessary) Wait until next HEG delivery.									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)									
Identified HEG problems will continue.									
27. Justification for Emerg									
NSIDC DAAC does not hat are not completing in an a								S	
	DF ⊠PVC ⊠VATC [DC ☐ IDG Test Cell [□EDC □ □Other	GSFC □Lal			SMC □A	K □JPL	_	
29. Board Comments:			30	. Wo	rk Assigned T	o: 31. C	CCR Closed Date:		
32. EDF/SCDV CCB Chair (Evelyn N. Nakamura /s	-	sposition: Ar Fv	oproved App vd/ECS	/Com	. Disapproved	l Withdrav	w Fwd/ESDIS ERE	3	
33. M&O CCB Chair (Sign/l Pamela Johnson /s/	Date): Dis 07/18/03	position: Ar	proved App	/Com.	. Disapproved	d Withdra	w Fwd/ESDIS ERE	3	
			vd/ECS						
34. ECS CCB Chair (Sign/D	Disp	osition: App	proved App/0	Com.	Disapproved	l Withdrav	v Fwd/ESDIS ERE	3	

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O

Fwd/ESDIS

ADDITIONAL SHEET

CCR #: 03-0511 Rev: — Originator: Derrick Clark				
Telephone: 301-925-1024 Office: 2028				
Title of Change: TE_6A.07_HEG.01				
Actions				
ClearCase				
Please make one SOL8 (sun5.8) tar file from the 6A07EBF1 baseline for the following binaries: /ecs/formal/STAGE/OSS/bin/sun5.8/resample /ecs/formal/STAGE/OSS/bin/sun5.8/hegtool				
Please name this tar file TE_6A.07_HEG.01				
Block 22&23 continued from page 1				
ECSed37567 SEV2 NSIDC Datapool HEG Orders impacting system resources ECSed37800 SEV3 EDF Lack of Shortname stops user from using HEG.				
PATCH DEPENDENCIES				
The new HEG tool can be installed on top of any previously delivered version of HEG.				
DAAC Installation Instructions:				
A. PRE-INSTALLATION:				
1. Copy the *SOL8* tar files into the <staging_area>/SOL8 directory</staging_area>				
2. Un tar the SOL8 tar file using the unix command tar -xfv				
B. INSTALLATION:				
1. login to the host where the .EcOsHg.pkg is installed (xxdps01)				
2 cd /usr/ecs/ <mode>/CUSTOM/bin/OSS</mode>				
cp <staging_area>/<sol8>/resample . cp <staging_area>/<sol8>/hegtool .</sol8></staging_area></sol8></staging_area>				
chmod 775 resample hegtool				
C. CONFIGURATION:				
None				
D. DATABASE:				
None				
E. POST-INSTALLATION:				
None				

IMPORTANT NOTES:

CM01AJA00 Revised 8/2/02

ECS